

## PO Job Risk Assessment

<b>Name(s) of Risk Team Members:</b> S. Boose, H. Diaz, R. Pisani, R. Gill (facilitator)	<b>Point Value → Parameter ↓</b>	1	2	3	4	5
<b>Job Title: Electrical &amp; Electronic Shop Work</b>  <b>Job Number or Job Identifier: PO-JRA-009</b>	<b>Frequency (B)</b>	≤once/year	≤once/month	≤once/week	≤once/shift	>once/shift
<b>Job Description:</b> Work in electrical and electronic shops	<b>Severity (C)</b>	First Aid Only	Medical Treatment	Lost Time	Partial Disability	Death or Permanent Disability
Training and Procedure List (Optional):	<b>Likelihood (D)</b>	Extremely Unlikely	Unlikely	Possible	Probable	Multiple
Rev. #: 0	Date: <b>February 15, 2005</b>					
<b>Stressors (if applicable, please list all):</b> Lighting, time schedules		<b>Reason for Revision (if applicable):</b>			<b>Comments:</b>	

				Before Additional Controls							After Additional Controls					
Job Step / Task	Hazard	Control(s)	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	Control(s) Added to Reduce Risk	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	% Risk Reduction
Electronic soldering	Temperature extremes burns to skin or eyes from iron or molten solder	Soldering equipment design and condition, Tier 1, eye protection, proper clothing	N	1	4	1	4	16								
	Chemical toxicity solder and fumes	Solder choice, small amounts of solder per operation, ventilation	N	1	4	1	1	4								
	Electrical shock	Soldering equipment design and condition, Tier 1, electrical cord inspection	N	1	4	2	1	8								

## PO Job Risk Assessment

				Before Additional Controls							After Additional Controls					
Job Step / Task	Hazard	Control(s)	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	Control(s) Added to Reduce Risk	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	% Risk Reduction
Electronic soldering (cont'd)	Reflex injury from burns or electrical shock	Soldering equipment design and condition, eye protection, proper clothing, Tier 1, electrical cord inspection, small amounts of solder per operation	N	1	4	2	2	16								
Electronic chassis assembly	Cuts and abrasions from sharp surfaces	Work gloves where needed, tool condition	N	1	2	1	4	8								
	Physics Hand Held Tools	See <a href="#">PO-JRA-016</a>	N	1	2	1	3	6								
Circuit board assembly – selection and placement of components	Eye strain	Proper lighting and magnifying lenses	Y	1	3	1	3	9								
	Injury from repetitive motions	Work breaks, switching tasks, ergonomic review, proper tools, tool condition	N	1	2	2	2	8								
	Cuts and abrasions	Proper tools, tool condition, proper lighting, clear work area, wear gloves when needed, Tier 1	N	1	2	1	2	4								
Circuit board and component cleaning	Physics Routine Chemical Use	See <a href="#">PO-JRA-017</a>	N	1	3	1	2	6								
Point to point wiring	Eye strain	Proper lighting and magnifying lenses	Y	1	2	1	3	6								
	Injury from repetitive motions	Work breaks, switching tasks, ergonomic review, proper tools, tool condition, Tier 1	N	1	2	2	2	8								
	Physics Hand Held Tools	See <a href="#">PO-JRA-016</a>	N	1	2	1	3	6								

## PO Job Risk Assessment

				Before Additional Controls							After Additional Controls					
Job Step / Task	Hazard	Control(s)	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	Control(s) Added to Reduce Risk	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	% Risk Reduction
Cable making – measuring and rolling out cable	Overexertion injuries caused by excessive lifting, pushing, pulling, holding, carrying	Squat lifting and bending over technique, training, use helper, Tier 1, clear work area	N	1	1	3	3	9								
Cable making – using cutting or crimping tools	Injury from repetitive motions	Work breaks, switching tasks, ergonomic review, proper tools, tool condition	N	1	1	2	2	4								
	Cuts and abrasions	Proper tools, tool condition, proper lighting, clear work area, wear gloves when needed, Tier 1	Y	1	1	1	3	3								
Low voltage testing and troubleshooting	Physics Electrical Work – Routine	See <a href="#">PO-JRA-006</a>	N	1	4	1	2	8								
High voltage testing and troubleshooting	Physics Electrical Work – High Energy	See <a href="#">PO-JRA-007</a>	N	1	3	2	2	12								
Manual lifting – electronic crates, power supplies, equipment, cable spools	Physics Manual Lifting	See <a href="#">PO-JRA-004</a>	N	1	3	3	3	27								
Further Description of Controls Added to Reduce Risk:																
*Risk:	0 to 20 Negligible	21 to 40 Acceptable	41 to 60 Moderate			61 to 80 Substantial			81 or greater Intolerable							